

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I - WATER SUPPLY

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Seasonal _____ ☐ Unknown
☐ Drilled ☐ Dug ☐ Other _____

MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the
 (public/private/other) water system?

Pump (if any): ☐ N/A ☐ Yes ☒ No ☐ Unknown
 Quantity: ☐ Yes ☒ No ☐ Unknown
 Quality: ☐ Yes ☒ No ☐ Unknown

If Yes to any question, please explain in the comment section below or with attachment.

WATER TEST: Have you had the water tested? ☐ Yes ☒ No
~~If Yes, Date of most recent test: _____ Are test results available? .. ☐ Yes ☐ No~~
~~To your knowledge, have any test results ever been reported as unsatisfactory~~
~~or satisfactory with notation? ☐ Yes ☐ No~~
~~If Yes, are test results available? ☐ Yes ☐ No~~
~~What steps were taken to remedy the problem? _____~~

IF PRIVATE: (Strike Section if Not Applicable):

INSTALLATION: Location: Behind house at the west end of stone wall

Installed by: Affordable Well Drilling, Inc

Date of Installation: June 21, 2023

USE: Number of persons currently using system: 3

Does system supply water for more than one household? ☐ Yes ☒ No ☐ Unknown

Comments: 330 feet, 3 gpm flow rate

Source of Section I information: Seller

Buyer Initials _____

Page 1 of 8

Seller Initials MG

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

SECTION II - WASTE WATER DISPOSAL

TYPE OF SYSTEM: ☐ Public ☒ Private ☐ Quasi-Public _____ ☐ Unknown

IF PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable):
~~Have you had the sewer line inspected? _____ ☐ Yes ☐ No~~
~~If Yes, what results: _____~~
~~Have you experienced any problems such as line or other malfunctions? _____ ☐ Yes ☐ No~~
~~What steps were taken to remedy the problem? _____~~

IF PRIVATE (Strike Section if Not Applicable):
Tank: ☒ Septic Tank ☐ Holding Tank ☐ Cesspool ☐ Other: _____
Tank Size: ☐ 500 Gallon ☒ 1000 Gallon ☐ Unknown ☐ Other: _____
Tank Type: ☒ Concrete ☐ Metal ☐ Unknown ☐ Other: _____
Location: South of stone wall below barn (not site shown on permit) OR ☐ Unknown
Date installed: 2001 Date last pumped: NA Name of pumping company: NA
Have you experienced any malfunctions? _____ ☐ Yes ☒ No
If Yes, give the date and describe the problem: NA

Date of last servicing of tank: NA Name of company servicing tank: NA
Leach Field: _____ ☒ Yes ☐ No ☐ Unknown
If Yes, Location: Same as tank
Date of installation of leach field: 2001 Installed by: Unknown
Date of last servicing of leach field: NA Company servicing leach field: NA
Have you experienced any malfunctions? _____ ☐ Yes ☒ No
If Yes, give the date and describe the problem and what steps were taken to remedy: NA

Do you have records of the design indicating the # of bedrooms the system was designed for? ☒ Yes ☐ No
If Yes, are they available? _____ ☒ Yes ☐ No
Is System located in a Shoreland Zone? _____ ☐ Yes ☒ No ☐ Unknown
Comments: Design is listed as 3 bedroom; 272 gal per day.
Source of Section II information: Seller

Buyer Initials _____ Page 2 of 8 Seller Initials  _____

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

SECTION III - HEATING SYSTEM(S)/HEATING SOURCE(S)

Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	Oil furnace	Wood stove		
Age of system(s) or source(s)	25 years	50 years		
TYPE(S) of Fuel	Oil	wood		
Annual consumption per system or source (i.e., gallons, kilowatt hours, cords)	800-1000 gallons OR 600-750 gallons	2-3 cords 4-5 cords		
Name of company that services system(s) or source(s)	ABT Plumbing & Heating	Don's Stove Shop		
Date of most recent service call	October 2025	2020		
Malfunctions per system(s) or source(s) within past 2 years	None	None		
Other pertinent information				

Are there fuel supply lines? ☒ Yes ☐ No ☐ Unknown
 Are any buried? ☐ Yes ☐ No ☒ Unknown
 Are all sleeved? ☐ Yes ☐ No ☒ Unknown
 Chimney(s): ☒ Yes ☐ No **2 Chimneys**
 If Yes, are they lined: ☒ Yes **Wood** ☐ No ☒ ~~UNKNOWN~~ **Oil**
 Is more than one heat source vented through one flue? ☐ Yes ☒ No ☐ Unknown
 Had a chimney fire: ☐ Yes ☒ No ☐ Unknown
 Has chimney(s) been inspected? ☐ Yes ☒ No ☐ Unknown
 If Yes, date: NA
 Date chimney(s) last cleaned: NA
 Direct/Power Vent(s): ☐ Yes ☒ No ☐ Unknown
 Has vent(s) been inspected? NA... ☐ Yes ☐ No ☐ Unknown
 If Yes, date: NA

Comments: **Woodstove chimney not in use since 2020-2021 season**

Source of Section III information: **Seller**

SECTION IV - HAZARDOUS MATERIAL

The licensee is disclosing that the Seller is making representations contained herein.

A. UNDERGROUND STORAGE TANKS - Are there now, or have there ever been, any underground storage tanks on the property? ☐ Yes ☒ No ☐ Unknown

~~If Yes, are tanks in current use? ☐ Yes ☐ No ☐ Unknown~~

~~If no longer in use, how long have they been out of service? _____~~

~~If tanks are no longer in use, have tanks been abandoned according to DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Are tanks registered with DEP? ☐ Yes ☐ No ☐ Unknown~~

~~Age of tank(s): _____ Size of tank(s): _____~~

~~Location: _____~~

Buyer Initials _____

Page 3 of 8

Seller Initials  _____

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

~~What materials are, or were, stored in the tank(s)?~~ _____

~~Have you experienced any problems such as leakage:~~ _____ ☐ Yes ☐ No ☐ Unknown

~~Comments:~~ _____

Source of information: Seller

B. ASBESTOS - Is there now or has there been asbestos:

As insulation on the heating system pipes or duct work?	☐ Yes	☒ No	☐ Unknown
In the ceilings?	☐ Yes	☒ No	☐ Unknown
In the siding?	☐ Yes	☒ No	☐ Unknown
In the roofing shingles?	☐ Yes	☒ No	☐ Unknown
In flooring tiles?	☐ Yes	☒ No	☐ Unknown
Other: <u>NA</u>	☐ Yes	☐ No	☐ Unknown

Comments: NA

Source of information: Seller

C. RADON/AIR - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown~~

~~Are test results available? ☐ Yes ☐ No~~

Results/Comments: NA

Source of information: Seller

D. RADON/WATER - Current or previously existing:

Has the property been tested? ☐ Yes ☒ No ☐ Unknown

~~If Yes: Date: _____ By: _____~~

~~Results: _____~~

~~If applicable, what remedial steps were taken? _____~~

~~Has the property been tested since remedial steps? ☐ Yes ☐ No ☐ Unknown~~

~~Are test results available? ☐ Yes ☐ No~~

Results/Comments: NA

Source of information: Seller

E. METHAMPHETAMINE - Current or previously existing: ☐ Yes ☒ No ☐ Unknown

Comments: NA

Source of information: Seller

Buyer Initials _____

Seller Initials  _____

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

F. LEAD-BASED PAINT/PAINT HAZARDS - (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)

Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
..... Yes ☐ No ☐ Unknown ☒ Unknown (but possible due to age)

If Yes, describe location and basis for determination: NA

Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: ☐ Yes ☒ No

If Yes, describe: NA

Are you aware of any cracking, peeling or flaking paint? ☐ Yes ☒ No

Comments:NA

Source of information: Seller

G. OTHER HAZARDOUS MATERIALS - Current or previously existing:

TOXIC MATERIAL: ☐ Yes ☒ No ☐ Unknown

LAND FILL: ☐ Yes ☒ No ☐ Unknown

RADIOACTIVE MATERIAL: ☐ Yes ☒ No ☐ Unknown

Other: NA

Source of information: Seller

Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - ACCESS TO THE PROPERTY

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of first refusal, life estates, private ways, trails, homeowner associations (including condominiums and PUD's) or restrictive covenants? ☒ Yes ☐ No ☐ Unknown

If Yes, explain: ROW/For use in common with the grantor herein certain water and certain sewer rights

Source of information: Deeds

Is access by means of a way owned and maintained by the State, a county, or a municipality over which the public has a right to pass? ☒ Yes ☐ No ☐ Unknown

If No, who is responsible for maintenance? NA

Road Association Name (if known): NA

Source of information: Seller

Buyer Initials _____ Page 5 of 8 Seller Initials  _____

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

SECTION VI – FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines “area of special flood hazard” as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:

Have any flood events affected the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: NA

Have any flood events affected a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: NA

Has any flood-related damage to a structure occurred on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: NA

Has there been any flood insurance claims filed for a structure on the property? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the dates of each claim: NA

Has there been any past disaster-related aid provided related to the property or a structure on the property from federal, state or local sources for purposes of flood recovery? ☐ Yes ☒ No ☐ Unknown

If Yes, indicate the date of each payment: NA

Is the property currently located wholly or partially within an area of special flood hazard mapped on the effective flood insurance rate map issued by the Federal Emergency Management Agency on or after March 4, 2002? ☐ Yes ☒ No ☐ Unknown

If yes, what is the federally designated flood zone for the property indicated on that flood insurance rate map?
NA

Relevant Panel Number: FEMA flood insurance rate map is outdated Year: 1997 (Attach a copy)

Comments: See FEMA and LandID Flood Maps

Source of Section VI information: Seller, FEMA Flood Map, LandID Flood Map

Buyer Initials _____ Page 6 of 8 Seller Initials MG

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

SECTION VII - GENERAL INFORMATION

Are there any tax exemptions or reductions for this property for any reason including but not limited to:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blind, Working Waterfront?.....
..... ☒ Yes ☐ No ☐ Unknown

If Yes, explain: Tree Growth

Is a Forest Management and Harvest Plan available?..... ☒ Yes ☐ No ☐ Unknown

Are there any actual or alleged violations of a shoreland zoning ordinance
including those that are imposed by the state or municipality? ☐ Yes ☒ No ☐ Unknown

If Yes, explain: NA

Equipment leased or not owned (including but not limited to, propane tank, hot water heater, satellite dish, water
filtration system, photovoltaics, wind turbines): Type: NA

Year Principal Structure Built: 1830's What year did Seller acquire property? 2010

Roof: Year Shingles/Other Installed: Unknown

Water, moisture or leakage: Yes

Comments: Vent flashing resealed in 2025.

Foundation/Basement:

Is there a Sump Pump? ☒ Yes ☐ No ☐ Unknown

Water, moisture or leakage since you owned the property: ☒ Yes ☐ No ☐ Unknown

Prior water, moisture or leakage? ☒ Yes ☐ No ☐ Unknown

Comments: _____

Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐ Unknown

If Yes, are test results available? NA .. ☐ Yes ☐ No

Comments: NA

Electrical: ☐ Fuses ☒ Circuit Breaker ☐ Other: _____ ☐ Unknown

Comments: Fuse box on 2nd floor is not in use and is disconnected

Has all or a portion of the property been surveyed? ☐ Yes ☒ No ☐ Unknown

If Yes, is the survey available? NA . ☐ Yes ☐ No ☐ Unknown

Manufactured Housing - Is the residence a:

Mobile Home ☐ Yes ☒ No ☐ Unknown

Modular ☐ Yes ☒ No ☐ Unknown

Known defects or hazardous materials caused by insect or animal infestation inside or on the residential structure
..... ☐ Yes ☐ No ☒ Unknown

Comments: NA

KNOWN MATERIAL DEFECTS about Physical Condition and/or value of Property, including those that may
have an adverse impact on health/safety: NA

Comments: NA

Source of Section VII information: Seller

Buyer Initials _____

Page 7 of 8

Seller Initials MG

PROPERTY LOCATED AT: 147 Mitchell Brook Road, Temple, ME 04984

SECTION VIII - ADDITIONAL INFORMATION

The new deed will include an easement over an area of one acre or less surrounding the oak grove with the memorial plaque, granting the current owner and their descendants a pedestrian right of way for access.

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ☐ Yes ☒ No

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

Authentisign

Matthew Goodman

10/22/2025

SELLER

DATE

SELLER

DATE

Matthew Goodman

SELLER

DATE

SELLER

DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER

DATE

BUYER

DATE

BUYER

DATE

BUYER

DATE